AREAS OF UTILIZATION

Pressure and temperature ranges

The temperatures provided are threshold values that must always be observed in tandem with the medium and the prevailing operating pressure. The permissible continuous temperatures are always within these thresholds.

1) Material code X = acid-proof, stainless steel:

Connecting screws 8.8 Fe/Ni 5P (or equivalent)

Material code Xc = all parts made of stainless steel!



